

MODEL NUMBER:


9500 Woodend Road | Edwardsville, KS 66111 | Tel: 913-951-3300 | Fax: 913-951-3399 | www.schierproducts.com

057-1080-02

ABOVE GRADE INSTALLATION

DESCRIPTION: Polyethylene Wastewater Sampling Port

page 4 of 5



Tools meeded: 7/16" Nut driver tool/bit (included), marker (included),

MOTE: To remove a component or adjust its position, the Upper

Band Clamp needs to be loosened or removed using nut driver bit. Loosened clamps should be re-tightened to 5-8 ft lbs. of torque

(same as a rubber no-hub coupling). The Lower Band Clamp is

are too long, make a circular line around the sidewall with

Adapters and risers should sit level with each other. Tighten upper clamps to keep riser/adapter assembly from shifting. Make alignment marks on the sidewalls at the top of all riser

are installed inside the main unit at the appropriate locations. Check if there needs to be any flow control adjustment at the

5. If tilting of the adapter is required to be flush with grade, do so

Schier recommends tilting only the adapter versus the entire

riser assembly to make sure your riser height and proper tank

there may be room for adjustment. As long as minimum and maximum insertion depths are maintained (see Figure 2), the


inlet diffuser (see general installation instructions).

tape measure and drill with 1/2" chuck, Jigsaw, circular saw or


reciprocating saw will be needed if risers need to be cut.

factory set and should not be adjusted or removed.

Riser Assembly Instructions/Steps



NOTES




>23" - 37-3/4"


>37-3/4" - 42-1/2"

>42-1/2" - 57-1/2"


>57-1/2" - 72"

SR24





page 3 of 5



GROUP

SUITE 106

EB#0004432

CONTRACT DATE: BUILDING TYPE: EXP. LT. MED-40 PLAN VERSION: SITE NUMBER: 309797 STORE NUMBER: 420630

TACO BELL

20711 SO. DIXIE. HWY CUTLER BAY, FL



Explorer Lite

GREASE TRAP DETAILS

PLOT DATE: 07-16-2018